


RF Electron Gun Mechanical Repair


Bill Jansma, Engineering Specialist Advanced Photon Source Argonne National Laboratory

2013 APS Accelerator Systems Division Seminar Series



WELCOME!









- BACKGROUND
- PROBLEMS ARISE
- IMPROVISED LASER SCANNER
- DISTORTION REVEALED
- REPAIR OF THE RF GUNS
- CATHODE CAPTURE
- SUMMARY
- CURRENT WORK

BACKGROUND


 Electron guns are used in electron microscopes, electron beam welders, old CRT monitors and televisions and as sources for particle accelerators







 Rf thermionic electron guns developed at SLAC / SSRL for the Stanford Positron Electron Accelerating Ring (SPEAR) project


- Rf thermionic electron gun / alpha magnet system subject of M. Borland's Ph.D. thesis
- System produces a bunched, high brightness electron beam
- Three generations of rf guns have been used as injectors at the APS since 1997
- APS procured three new rf guns in 2001




APS main injector layout. Trajectories in the alpha magnets are to scale.








- Cathode heated 800° C to 1,200° C
- Electrons emitted off cathode into cavity energized by microwaves
- Electrons accelerated by microwaves and injected into the LINAC




PROBLEMS ARISE


- Cathodes replaced in 2009; temperature and reflected power problems arose soon after
- Two rf guns failed in 2010 due to excess reflected power; spare rf guns were installed
- Further failures could limit capabilities; worst case temporarily suspend APS operations





- Inspection of cathode cartridges revealed distortion
- Rf gun mating surfaces suspected to be distorted as well
- Cathode mating surface difficult to reach, 75 mm in from flange opening






- No instrument available to profile the surface at the needed resolution
- Improvised measurement system developed to measure mating surface

IMPROVISED 2-D LASER SURFACE SCANNER

- Developed using equipment on-hand at APS
- Two Keyence laser sensors measure orthogonal axes
- Scanning sensor mounted to vertical translation
- Synchronous data output







- Coordinates ascertained by combining the data in spreadsheet
- Laser signal reflected from any surface on to a CCD array

Laser Displacement Sensors

- LK-G 152 and LK-G 157 sensors
- Range of +/- 40 mm at 150 mm
- 0.5 μm resolution
- Data recorded using Keyence LK-Navigator freeware
- Diffuse or specular surface reflectivity
- Capable of measuring through a transparent medium such as glass







Vertical Translation

- Indi-Square model 18 used for vertical translation
- Translation accuracy is 2.5 µm over 500 mm of travel
- Designed to accept a typical dial indicator head
- Sensor head weighs 290 grams;
 Counterweight added for balance
- Despite added weight the translation was smooth and precise


Orientation & Measurement

- Rf gun bodies rested in v-blocks
- Primary surface placed at optimum distance from sensor head
- Gun bodies set parallel to translation
- Scans across azimuth angles of 0, 45, 90 and 315 degrees
- Common reference plane allows overlay of scans across different angles



Data Collection and Processing

- Data collected using the LK-G3001 controller and laptop with LK-Navigator freeware
- Saved as a .csv file; opens as a single column; cut and pasted into a coordinate worksheet






- Synchronous measurement mode
- Coordinates adjusted to fit common centerline; Overlayed to produce an abstract 3-D view in a 2-D graph


Error Analysis

- Accuracy initially estimated to be +/- 5 μm
- Further analysis indicates accuracy is closer to +/- 15 μm
- Decrease from initial estimate attributed to noise produced by the motion of the sensor head during translation
- Accuracy might be improved through refinements in motion control for the translation



DISTORTION REVEALED


- Coordinate plots revealed distortion.
- Flat mating surface seals rf cavity from leakage and acts as a thermal and electrical conductor.
- Distortion caused by over-tightening of eight #4-40 screws that secure the cartridge within the gun body; now thought to have originated with the vendor.
- Source of problems discovered, but what now?




REPAIR OF THE RF GUNS

- Alternatives were explored including replacement, modification, and repair.
- Replacement and/or modification would be costly







- Decision made to repair the damaged guns
- Special retraction tool designed by E. Traktenberg was tested successfully on a mockup




MOCKUP TEST RESULTS






- Efficacy of the tool proven in the mockup test
- Successful repair was performed on two rf guns in March / April 2011








Mating Surface Prior To Repair




Mating Surface After 500 μm Retraction




 Polar plot used to identify locations for push back




Tools for retraction and push back



Mating Surface After Push Back




Final Profile of Mating Surface After Polishing



MODIFIED CATHODE CAPTURE


- Damage caused by over-tightening the cathode cartridge
- Torque of 0.2 inch pounds will deflect surface by 25 μm






- Screws seated against primary retaining ring with little / no torque applied
- Second retaining ring screwed to primary ring, clamping the eight primary screw heads between the two rings

SUCCESS!



- After repair the rf guns were rigorously tested in the APS Injector Test Stand
- The 3G1 and 3G3 guns are currently being operated in the APS Main Injector




SUMMARY

- In 2009 problems arose in the APS rf thermionic electron guns after replacement of ageing cathodes
- To identify and characterize the problems a laser surface scanner was improvised at the APS using equipment on-hand
- A special tool was designed to retract the damage discovered in the rf guns
- New cathode cartridge capture system prevents further damage
- Repairs not perfect; goal to restore functionality; successful in this regard
- Both guns still operational after almost 2 years
- Substantial savings; rf thermionic electron guns cost about \$70,000 each

CURRENT WORK

- Two more rf guns underwent the repair process in 2012
- 3G2 and BBC guns had same damage to cathode mating surface
- Damage found in the 3G2 gun indicates problem originated at vendor; gun had never been opened by APS personnel
- BBC gun repair supports graphene window test



Ballistic Bunch Compression Rf Gun

THANK YOU FOR ATTENDING!

Acknowledgements:

Emil Traktenberg, Nick Sereno, Stan Pasky, Bran Brajuskovic, John Hoyt, Jeff Dooling, Wayne Michalek, Scott Wesling