4-28-04 Secter 5 pump hrs

Scheduled Bearing change
Replace castors on vessel
Auto Restart Modification (Dan & Glenn)
Replace Power supply

Disassembled pump -

Impeller gap set at .020
Visual inspection - OK

Cleaned shaft housing with alcohol

Changed bearings per Barber Nichols -
reassembled.

Leak checked OK

Replace 24V Power supply
located in MANS Distribution Rack
(power indicator lights flashing)

Power Supply - Protek Model PU 40-14S

Pump down all vacuum jackets

Bearings run in - No problems