4-22-04 Sector 9 pumphrs-24,750

Scheduled Bearing Change
Replace Heater stick (Burned out by user)
Replace Casters on vessel

Impeller gap set at .020

Replaced Bearings, Cleaned
Motorshaft housing, with al

Bearingchange done per Barber Nichols manual
Reset gap to .020
Replaced screws for impeller housing

Leak check - Small leaks
found on compression fittings for
Level Probe and Heater stick, Tightened
fittings Leak check OK.

Pump down Vacuum Sackets

Bearings run in - No Problems

Further notes by R. Dartnest (5-27-04)
- work performed by D. Ferguson + D. Burke
- pump down on jackets includes vessel + 3 bayonets