4-25-04 Sector 13 pump hours 5-33,295.0

Scheduled Bearing change
Change Castors on Vessel
Restart Timer Modification

Disassembled pump

Impeller gap set at .020

Replaced Bearings, cleaned motor
Shaft housing, slight grease residue
from bearings (top end) with alcohol
Reset gap to 0.020
(Bearing change per Barber Nichols)

Leak checked OK

No other problems found on Cooler

Timer Restart Mod done by G. Manor