SECTOR 17 Thurs / Fri 5-20/21-2004

Dan Burke + Dale Ferguson

- 5-20 found leak on LN_2 supply bayonet
- Removed pumpout plug + repaired O-ring (added vac grease only)
- opened user vac station and pumped overnight
- ice ball gone on Friday

- 5-21 pumped vessel jacket w/ user vac station
- vac station failed (vented)
- allowed LN_2 to HP loop to reach 90 psig (reported by User)
- user rectified vac station problem + relieved pressure on HP loop
- system returned to normal operation

DAN