

OXFORD CRYOGENIC PUMP  
SERVICE REQUEST

Note: At this time normal servicing and routine replaceable parts will be a service of the APS.

DATE OF REQUEST: Aug 25 2004  
SECTOR NUMBER: 33 ID  
SERIAL NUMBER: 6E95  
PUMP STYLE: B  
PUMP AVAILABLE FOR SERVICE ON: 27 Aug 2004  
PUMP TO BE RETURNED BY: 15 Sept 2004  
CURRENT PUMP HOURS: \_\_\_\_\_  
HOURS SINCE LAST SERVICE: \_\_\_\_\_

- Scheduled pump bearing change
- Burst disk blown, why? \_\_\_\_\_
- Buffer level probe failure
- Vessel level probe failure
- Heater probe failure
- Buffer leaking excessively, at what rate: \_\_\_\_\_
- Pressure sensor failure
- Electronics control rack failure, describe: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- Vacuum leaks. Identify locations and for how long: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- Other

Please contact Bob Dortwegt at 2-6058/4-1740 or by email ([dortwegt@aps.anl.gov](mailto:dortwegt@aps.anl.gov)).