

Safety Inspection of 10/15/03 by E. Gluskin and J. Alicz

Sector 7 LOM Office Area

The following items were identified during the inspection:

1. Noteworthy Practice: The general area was found to be in good order.
2. The office needs improved housekeeping, and the experimental setup in the office does not appear to be in a stable condition (see photo below).



3. The electrical rack located in front of an office door should be repositioned to provide easier access to and from the office (see photo below).



Also, the cables from the electrical rack should be repositioned so that they do not create a tripping hazard in front of the office door (see photo below).



4. Reminder: Empty boxes should be removed from the area.
5. The plotter in the hallway also needs to be relocated to a more suitable storage area (see photo below).



Sector 8 LOM Office Area

The following items were identified during the inspection:

1. The table needs to be repositioned to create a wider aisle between the table and the bookshelf (see photo next page). **Note: this item was immediately corrected.**



2. General housekeeping in the area needs to be improved.
