

Safety Inspection of 11/26/03 by E. Gluskin and J. Alicz



Sector 7 Beamlines

The following items were identified as needing corrective action:

1. Cables on floor downstream from 7-ID-B need to be better organized (see photo below).



2. Overhead cable trays should be installed to accommodate hanging cables and cables attached to beam pipes (see photos below).



3. General housekeeping in this area requires improvement (see photo below).

