5-1-04 Process Spare #1

During Pump maintenance, planning to use control rack to run in bearings for the bearing change performed on sectors 5, 9, 13, and 20. After change completed on sector 9 it was discovered that the process spare control rack would not operate the pump. All connections were checked, Problem was found to be a loose wire on Plug # 5K1 Cooler Power. Reconnected wire and problem solved.