

Requester Denis Keane 2-0224

OXFORD CRYOGENIC PUMP
SERVICE REQUEST

Note: At this time normal servicing and routine replaceable parts will be a service of the APS.

DATE OF REQUEST: 4-19-2004
SECTOR NUMBER: 5
SERIAL NUMBER: AMG01100/57 DND
PUMP STYLE: Series C
PUMP AVAILABLE FOR SERVICE ON: 4-21-2004
PUMP TO BE RETURNED BY: 5-20-2004
CURRENT PUMP HOURS: 48497.2
HOURS SINCE LAST SERVICE: 4957

- Scheduled pump bearing change
- Burst disk blown, why?
- Buffer level probe failure
- Vessel level probe failure
- Heater probe failure
- Buffer leaking excessively, at what rate: _____
- Pressure sensor failure
- Electronics control rack failure, describe: 24V power supply ripple
REPLACE 24V SUPPLY

- Vacuum leaks. Identify locations and for how long: _____

Other NEW RESTART PACKAGE INSTALL - PARTS ON ORDER

Please contact Bob Dortwegt at 2-6058/4-1740 or by email (dortwegt@aps.anl.gov).