

OXFORD CRYOGENIC PUMP
SERVICE REQUEST

Note: At this time normal servicing and routine replaceable parts will be a service of the APS.

DATE OF REQUEST: 2-24-04
SECTOR NUMBER: 13 MIKE JAGGER
SERIAL NUMBER: Series C
PUMP STYLE: _____
PUMP AVAILABLE FOR SERVICE ON: April 22, 2004
PUMP TO BE RETURNED BY: May 6, 2004
CURRENT PUMP HOURS: 33,295.6
HOURS SINCE LAST SERVICE: _____

- Scheduled pump bearing change
- Burst disk blown, why?
- Buffer level probe failure
- Vessel level probe failure
- Heater probe failure
- Buffer leaking excessively, at what rate: _____
- Pressure sensor failure
- Electronics control rack failure, describe: Restart timer YES
- _____

- Vacuum leaks. Identify locations and for how long: _____

Whatever needs updating!
→ Per telecon w/ Patti N.

Other Please do not service the heater on the cryo pump since it doesn't get used. Please contact Bob Dortwegt at 2-6058/4-1740 or by email (dortwegt@aps.anl.gov). Thank you.

→ ~~B3189~~
3254