

Diagnostic Meeting Notes 1/21/05

Subject: Current Status

Date: 1/21/05

Attendees: Bingxin Sushil Al Brian

Action Items:

- BEAM DETECTOR
 - MOVE THE BOTTOM BEAM FOR GREATER STRENGTH
 - TACK WELD 1x2 BAR ALONG TOP FOR TOP PLATE MOUNTING SURFACE
 - HINGE PLATE MAY NOT HAVE ENOUGH ROOM TO CLEAR ISLE AROUND TABLE
 - DOUBLE HINGE THE DOOR?
 - END OF MONTH RELEASE IF POSSIBLE
 - AS OF 1-24-05 NOON WORKSPACE STILL HAS NOT BEEN RESTORED

- PINHOLE
 - CHECK ABOUT IF THE RFQ WENT THROUGH FRANK
 -