

# Machine Studies

## Schedule for Run2-2,2000

May 16th, 0800 - 1600

<b>Time</b>	<b>Descriptions</b>	<b>Studiers</b>	<b>SRStatus</b>
<b>Tuesday, 05/16/00</b>			
<b>0800-1000</b>	<b>Linac controlled access: RG2 kicker noise inspection</b>	<b>Pasky</b>	<b>No beam</b>
<b>1000-1130</b>	<b>Recover linac/PAR beam</b>	<b>OPS</b>	<b>No beam</b>
<b>0800-1200</b>	<b>SR power supplies: S24A:S2, S19A:V2, dipole trims</b>	<b>PS group</b>	<b>No beam</b>
<b>0800-1030</b>	<b>SR Zone E Authorized Access for ID32 EPS fix</b>	<b>ISI group</b>	<b>No beam</b>
<b>1030-1100</b>	<b>Turn on Zone E PS</b>	<b>OPS</b>	<b>No beam</b>
<b>1200-1330</b>	<b>Characterize S25 prototype bpm XAXSTF in ID33/34</b>	<b>Lill, Singh</b>	<b>Stored beam and injection</b>
<b>1330-1530</b>	<b>Retune EMW correction in ID11</b>	<b>CY</b>	<b>Stored beam and injection</b>
<b>1530-1600</b>	<b>Recover for User beam</b>	<b>OPS</b>	<b>Stored beam and injection</b>