


JJ X-Ray Tungsten Carbide slit type 3 <u>dwg961201f1</u>						
Vexta steptomors type PK244M-01B 0.9amp	Black	Yellow	Green	Red	White	Blue
M1= pin 1-6	⎓⎓⎓⎓		⎓⎓⎓⎓			
	1	2	3	4	5	6
M2= pin 7-12	⎓⎓⎓⎓		⎓⎓⎓⎓			
	7	8	9	10	11	12
M3= pin 14-19	⎓⎓⎓⎓		⎓⎓⎓⎓			
	14	15	16	17	18	19
M4= pin 20-25	⎓⎓⎓⎓		⎓⎓⎓⎓			
	20	21	22	23	24	25
25 pins Sub D plugs						



Split-up cables for step-drives

1	1	Cabel diagram		
Pos	Pc	Name	Mat. or Dwg. nr.	Remarks
Date	Constr.	<i>JJ X-Ray</i> Danish Science Design		Scale
20-08-01	Jens Linderholm			1 : 1
Surface	Cabels f Tungsten-carbide-slit type 3		4- 961211f4	