

TECHNICAL NOTE **WORK REQUEST NO: 17406**

Install flow orifice and transmitter for laser chiller.

Engineer: R. Dortwegt

Chief Technician: R. Ferry (work supervisor)

Radiation Safety System: no

Red tag: no

When performing this work:

1. No work shall until the engineer and chief technician have discussed the work.
2. Ensure that the power cord for the chiller for the laser is removed from the power outlet.
3. Care must be taken when climbing the ladder to access the mezzanine where the chiller is installed.
4. The flow orifice will be one that is rated at 6 gpm @ 50 inWC.
5. Wire PLC per instructions from R. Putnam and R. Ferry. There must be no exposed 120VAC wiring in the cabinet when making these connections.