

Machine Studies

Schedule for Run2-6,2000

June 13th, 0800 - 1600

Time	Descriptions	Studios	SRStatus
Tuesday, 06/13/00			
0800-1530	Repair of helios disk farm	Sidorowicz	No beam
0800-1000	Check RF gun #1 kicker Work on L4QM7	J. Wang Markovich	No beam
0830-0930	Zone E access for ID34 examination	J. Grimmer	No beam
0830-0930	Zone F access for scraper cable measurement	J. Stevens	No beam
1200-1430	Standby study: New filter/comparator on S25B:P1	B. Lill O. Singh	Stored beam and injection
1430-1530	Standby study: Dynamic orbit feedback development	C. Schwartz F. Lenkszus	Stored beam and injection
1530-1600	Recover for User beam	OPS	Stored beam and injection