

Machine Studies

Schedule for Run4-4,2000

Nov 23th, 0800 - Nov 24th, 0800

Time	Descriptions	Studiers	SRStatus
Thursday, 11/23/00			
0000-0200	Software tests and leave instructions.	Emery	Stored beam and injection
0200-0700	Offset measurements	OPS	Stored beam and injection
0800-1200	General heating maintenance.	Kailus	Stored beam and injection
0700-1500	Offset measurements/Operator training	OPS	Stored beam and injection
1500-2400	Offset measurements/Operator training	OPS	Stored beam and injection
Friday, 11/24/00			
0000-0800	Offset measurements/Operator training	OPS	Stored beam and injection