## **Machine Studies**

## Schedule for Run1-4,2003

February 18th, 0800 - February 18th, 1600

Time	Descriptions	Studiers	SRStatus
	Tuesday, 02/18/03		
0800-1000	Gespac card replacement in sector 9.	Fors	No beam
	Continue inspection of shorted klixons.	Fors	No beam
	PEK4 DAC dropping investigation.	Fors	No beam
	Sector 38 RAW supply checking.	Fors	No beam
0800-0815	SR WG switch to RF3 and RF4.	Cours	No beam
0800-0900	Linac water station shutdown.	Dortwegt	No beam
1000-1200	S38 cavity 4 tuner control test.	Dimonte Harkay Horan	Stored beam and injection
1200-1300	Steering the beam to investigate ceramic chamber temperature.	Decker	Stored beam
1300-1430	Data pool orbit correction.	Emery	Stored beam and injection
1430-1500	Switch back to RF1 (if required)	RF	No beam
1500-1600	Prepare for user operation.	Yao	Stored beam and injection