Machine Studies/Intervention Schedule for Run 1998-5-1

October 16, 1998 0800 — October 22, 1998 0800

Time	Monday, October 19, 1998	Studiers
1000-1400	Power supply modifications	PS Group
1400-2000	Establish beam in SR	Borland
	Tune injection	
	BPM Intensity dependence	
2000-2400	35BM photon monitor recommissioning	Lumpkin
		Yao
Time	Tuesday, October 20, 1998	Studiers
0000-0800	RF conditioning	OPS
0800-1400	Contingency: machine tuning and operational measurements	Borland
1400-1600	Cross calibration of Nb and X-ray BPMs	Singh
1600-2400	Rogue microwave mode	Decker
1000 2100	Rogue mierowave moue	Decker
		~
Time	Wednesday, October 21, 1998	Studiers
Time 0000-0800	Wednesday, October 21, 1998 RF conditioning	Studiers OPS
	RF conditioning	OPS
0000-0800	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements	OPS Pasky Sereno Lumpkin
0000-0800 0800-1200	RF conditioning rf gun beam into PAR and booster Bunch cleaning	OPS Pasky Sereno
0000-0800 0800-1200	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements	OPS Pasky Sereno Lumpkin Yao OPS
0000-0800 0800-1200 1200-1600 1600-2000	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements (floor coordinator required)	OPS Pasky Sereno Lumpkin Yao
0000-0800 0800-1200 1200-1600	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements (floor coordinator required)	OPS Pasky Sereno Lumpkin Yao OPS Yao Harkay
0000-0800 0800-1200 1200-1600 1600-2000	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements (floor coordinator required)Operator traning	OPS Pasky Sereno Lumpkin Yao OPS Yao
0000-0800 0800-1200 1200-1600 1600-2000	RF conditioning rf gun beam into PAR and boosterBunch cleaningBunch purity measurements (floor coordinator required)Operator traning	OPS Pasky Sereno Lumpkin Yao OPS Yao Harkay
0000-0800 0800-1200 1200-1600 1600-2000 2000-2400	RF conditioning rf gun beam into PAR and booster Bunch cleaning Bunch purity measurements (floor coordinator required) Operator traning Electron cloud	OPS Pasky Sereno Lumpkin Yao OPS Yao Harkay Rosenberg