

## Motor drive list for DEEs

This is not a comprehensive list. If your driver model does not appear below, it must be brought to the APS-ESC for evaluation.

Manufacturer	Non-Hazardous models	Hazardous models
ACS	SPD-6U SPD-6B SPD-32M SPD-3M SPD-35 SPD-35M MCB-4B SPD 5F SPC-3	
Applied Motion Products	2035-O	
CARS	BP-8000	
Compumotor	OEM350 OEM650 OEM750	OEMZL4 S6 Series E-AC
Delta-Tau	AMP-1	
Faulhaber	MCDC2805 SLC3002A	
Galil	AMP-20341 AMP-2054O Econo	
Industrial Devices		Next Step

Manufacturer	Non-Hazardous Models	Hazardous Models
<b>Kohzu</b>		MD-501A MD-501C MD-551A MD-535G AAM-21 HLD-4 PD-6APS PD-8A PD-8B SC-80 5 phase
<b>Newport</b>	8703 ESP300 ESP301 MM4005 PM500 XPS	
<b>Oriental Motors (Vexta)</b>		CSD 5814-T DFC 5107T PD-501H PD-501S RKD514H-A RKD514L-A RKD514W
<b>Parker</b>		D(P)DS 13-2 RAMS Zeta 4 Zeta 8 Zeta 12
<b>Phytron</b>	SinCos ZSO ZSX ZSX 93-70 ZMX	
<b>Superior Electric</b>		Slo-Syn PDM 4 Slo-Syn PDM 8