

Date: April 2, 2004

Subj: APS drawing [25040101-570201](#)
PAR-RF bellows

Spare status: Two spares complete and vacuum certified
Stored in Bldg 382 (see Fig. 2)



Fig. 1: Storage location of spare chamber in 382
(open cabinets on mezzanine)



Fig. 2: Photo of Spare Bellows
(Dwg [25040101-570201](#))

Further details:

- Installed on downstream end of fundamental RF cavity chamber (see Fig. 3).




Fig. 4: RF bellows as installed in PAR.