

# AOD Safety Inspection Report

Building No: 432

Location: MHATT-CAT, hutches and beamlines, sector 7

Inspected by: Elroy, Jeff Alicz, and Eric Landahl

Date Inspected: 5-23-05

Report created by: <u>E. Chang</u>			Date Created: <u>5-24-05</u>	
Safety Issues, Administrative Items, and Miscellaneous				
No.	Description	Specific Location	Owner	Date Completed
1	Housekeeping – clean up cables on floor	D020	MHATT-CAT	
2	Small drill press – needs an anti-restart device to prevent accidental start ups	D020	Elroy	<b>done</b>
3	Flammable liquids storage cabinet – recommend attaching a ground wire to the cabinet	D030	MHATT-CAT	done
4	GFCI '05 test on fume hood	D030	Floor Coordinators	<b>done</b>
5	No deficiencies detected	7 BM-A, ID-A	MHATT-CAT	
6	Under construction – hutch extension, will be a laser laboratory	7 ID-D	MHATT-CAT	
7	Oxygen monitor display is erratic	7 ID-B	Jeff Ullian	
8				
9				
10				
11				
12	<b>Bold notes added by ED</b>			